

Building: Pump Stations
262 & 476 Sunapee St.
Newport, New Hampshire

| Cond | dition |
|------|--|
| 1 | Fully operational, new, recently replaced |
| 2 | Fully operational, 0-25% of life expectancy used, no issues, no concerns, |
| 3 | Fully operational, 25-50% life expectancy used, periodic problems |
| 4 | Operational, 50-75% life expectancy used, occasional problems, frequent repairs needed |
| 5 | Operational only with constant attention, 100% life expectancy used, failure imminent |

Priority is scaled 1-10 with 1 being urgent

| Architectural | | | | | | | |
|---------------|-----------|-----------|--------------------------------|----------|---------------|-----------------------------|--------|
| | | | | | | | |
| | Equipment | Condition | Est. Remaining Service Life | Priority | Cost Estimate | Remarks & Recommendations | Photos |
| | | | | | | 476 Sunapee Pump Station | |

| equipment | condition | Est remaining Service life | priority | cost | remarks &recommendations | |
|-----------|-----------|-------------------------------|----------|------|-----------------------------|--|
| | | | | | 262 Sunapee Pump Station | |

| Structural | | | | | | | |
|------------|---|--|---------------------------------|--|---|--|--|
| | enclosure, which in turn mounted to a concrete h | is contained within a ousekeeping pad. The | wood stockad installation al | e fence enclosure. The lso includes an old oil ta | manholes are of concrete mank and a length of corruga | • | erator is supported on steel dunnage, s a container for on-site storage of |
| | Structural issues: Man Holes - Minor crack evidence, but the condit | | e concrete mar | nhole covers was noted | , particularly around the acc | cess hatches. Several previous atte | mpts to address this condition are in |
| | Oil Tank foundation - Th | e oil tank is presently | out of service | . The concrete block fo | undation is inadequate – th | s tank installation should be remov | ved if it is no longer required. |
| | | | | | | (also of precast construction) a pac were no structural deficiencies of n | |
| | Equipment | Condition | Est. Remaining Service Life | Priority Cost Estimate | | | |
| | | | | | | | |
| | | | | | | | |

| equipment | condition | Est remaining Service life | priority | cost | remarks &recommendations | | |
|-----------|-----------|-------------------------------|----------|------|--------------------------|--|--|
|-----------|-----------|-------------------------------|----------|------|--------------------------|--|--|

| al | | Est. Remaining | | | | |
|---|---|-----------------|----------|---------------|---|--|
| Equipment | Condition | Service Life | Priority | Cost Estimate | | |
| 900, 275 Gallon diesel fuel tank (262 Pump Station) | 4 Operational, 50- 75% life expectancy used, occasional problems, frequent repairs needed | 2 to 5 Years | 4 | \$1,500 | Supplies diesel fuel for generator. Tank is mounted on cement blocks that are stacked up two high. Tank is in need of exterior painting. Tank has no containment method in place. | |

| Electrical | | | | | | | |
|------------|---------------------|---|--------------------------------|----------|---------------|---|--|
| | Equipment | Condition | Est. Remaining Service Life | Priority | Cost Estimate | Remarks & Recommendations | |
| mou | 9,Three 25 KVA pole | 2 Fully operational, 0-25% life expectancy used, no issues, no concerns | 15 Years | 10 | | Provides power through overhead service to pole within Pump Station grounds. Maintained by power supplier. | |

| equipment | condition | Est remaining Service life | priority | cost | remarks &recommendations | |
|--|---|-------------------------------|----------|---------|---------------------------------|--|
| 258,Electrical Meter (476 Pump Station) | 2 Fully operational, 0-25% life expectancy used, no issues, no concerns | 15 Years | 10 | | Maintained by power supplier. | OR OF THE PROPERTY OF THE PROP |
| 257,Panelboard L 120/240v single phase panelboard (476 Pump Station) | 2 Fully operational, 0-25% life expectancy used, no issues, no concerns | 15 Years | 10 | \$3,000 | Located inside of an enclosure. | |
| | | | | | | SENENS PERSONAL STREET |

| equipment | condition | Est remaining Service life | priority | cost | remarks &recommendations | |
|--|---|-------------------------------|----------|----------|--|--|
| 255,40 KW diesel generator pad mounted Make: Cummins Model #DGND5938549 (476 Pump Station) Install date unknown. | 3 Fully operational, 25-50% life expectancy used, periodic problems | 10 Years | 10 | \$24,000 | SOUTH NO. KO70127177 SCHOOL C SOUTH NO. KO70127177 SCHOOL SOUTH SEAR OF SOUTH SEAR SEARCH SEA | |
| 578,Main disconnect and generator transfer switch (262 Pump Station) | 3 Fully operational, 25-50% life expectancy used, periodic problems | 10 Years | 10 | \$3,000 | | |
| 577,Three - 15 KVA pole mounted transformers (262 Pump Station) | 2 Fully operational, 0-25% life expectancy used, no issues, no concerns | 15 Years | 10 | | Provides power through overhead service. Maintained by power supplier. | |

| equipment | condition | Est remaining Service life | priority | cost | remarks &recommendations | |
|--|---|-------------------------------|----------|----------|--------------------------|--|
| 576,75 KW diesel generator pad mounted MAKE: Consolidated Power Model: 75D8T (262 Pump Station) | 2 Fully operational, 0-25% life expectancy used, no issues, no concerns | 15 Years | 10 | \$50,000 | Unknown date of install. | |

Site

262 Sunapee: Is a gravel road that appears adequate for the use.

476 Sunapee: There is an existing paved access from Whipple Road that leads to the pump station. Pavement appears in relatively good condition with no obvious deficiencies visually noted.

| Equipment | | emaining ice Life Priority | Cost Estimate Remarks & Recommendations | Photos |
|-----------|---|-------------------------------|---|--------|
| 476 | 1 | 15 10 | There is an existing paved access from Whipple Road that lead to the pump station. Pavement appears in relatively good condition with no obvious deficiencies visually noted. | |
| 262 | 1 | 15 10 | Is a gravel road that appears adequate for the use. Occasionally grade and add gravel. | |